

WARRANTY - HEAT TRACE PANELS - 3 YEARS



Brace Integrated Services agrees to fully repair any ATCOM Heat Trace Panel that fails to function within three years of the original invoice date.

A 'failure to function' is defined as the inability to execute features described in the User Manual and/or Project Proposal.

All associated costs will be covered under the warranty:

- On-site panel technicians
- Travel & lodging
- Panel parts
- Shipping fees
- Tools

The repair time-frame will depend entirely on the panel issue. Brace will submit a repair plan to the consumer within 1 week of discovery.

In the rare case that the panel is rendered unrepairable due to a natural disaster, plant accident, or extreme misuse, this warranty will void. Brace will then meet in-person with the consumer to discuss further options.

Brace is not liable for any incidental, consequential, or business interruption losses/damages.